

this document downloaded from

vulcanhammer.info

the website about
Vulcan Iron Works
Inc. and the pile
driving equipment it
manufactured

Visit our companion site
<http://www.vulcanhammer.org>

Terms and Conditions of Use:

All of the information, data and computer software ("information") presented on this web site is for general information only. While every effort will be made to insure its accuracy, this information should not be used or relied on for any specific application without independent, competent professional examination and verification of its accuracy, suitability and applicability by a licensed professional. Anyone making use of this information does so at his or her own risk and assumes any and all liability resulting from such use. The entire risk as to quality or usability of the information contained within is with the reader. In no event will this web page or webmaster be held liable, nor does this web page or its webmaster provide insurance against liability, for any damages including lost profits, lost savings or any other incidental or consequential damages arising from the use or inability to use the information contained within.

This site is not an official site of Prentice-Hall, Pile Buck, or Vulcan Foundation Equipment. All references to sources of software, equipment, parts, service or repairs do not constitute an endorsement.

中华人民共和国石油公司海洋分公司

PETROLEUM CORPORATION OF THE PEOPLE'S REPUBLIC OF CHINA

OFFSHORE BRANCH

P. O. BOX: 501
TANGGU, TIANJIN
TELEX: 25165 OBPCC CN
TELEPHONE: 2128 TANGGU
CABLE ADDRESS: 3189 TANGGU

MEMORANDUM

Mr. Pem. M. Warrington was invited by OFFSHORE BRANCH, PETROLEUM CORPORATION
of P.R.C. for checking the products of Contrat No. 81-CPCOB-002 on ~~Feb.~~^{March} 25th,
1982. Find proleums as follow:

A. Missing parts

- | | |
|---|-------|
| a. 22F0126 Open steam chamber head bracket washer | 2 pcs |
| b. Secondary air switch | 1 pc |
| c. Water gauge set | 1 set |
| d. Water gauge glass | 3 pcs |

B. Find low water alarm for boiler broken at panel

C. Find following parts of boiler rusted

- Swirler
- Front bearing
- rear bearing
- Blower shaft
- Shaft of modutrol motor rust seriously, can't turn now.

Mr. P. M. Warrington will make all effort to settle above problems.

OFFSHORE BRANCH
PETROLEUM CORP. of P.R.C.


VULCAN IRON WORKS

/S/

/S/

装
订
线

IF THIS PLACEMENT
CORRECT? ADVISE WHERE
PRE HEATER SHOULD
GO.



BOILER: INSTALLED ON DECK TEMP. ADVISE
ON BASIC PIPING SCHEME AND PLACEMENT
OF PUMP, TANK, PRE-HEATER.

VARI-CYCLE - ADVISE ON HOOKUP